


Sub-Zero Digital Hygrometer

Instructions for Use

The Sub-Zero Digital Hygrometer will accurately report humidity to +/- 2% at 50% - 80% RH (relative humidity). To activate this unit, simply remove the vinyl tab located in the battery door on the bottom left of the unit. The LED screen should turn on and show the humidity readings.

If the screen does not turn on, remove the battery by opening the cover located on the back of the unit. Make sure the battery is installed properly and makes contact with the silver metal contact. If the unit will not turn on, replace the battery.

- Measures 2.125" L x 3.375" W x .375" D
- Accurate to +/- 2% at 50% - 80% humidity



SUB-ZERO GROUP, INC.
800-222-7820
www.SUBZERO-WOLF.com



9003698 REV A